



## Inspect your fuel pump impulse line!

We have seen where the hose seems on the short side and develops a crack at the nipple coming off the fuel pump, this can create a bad hesitation and or bog most noticeable on hard landings.





We suggest replacing impulse line with a 2" longer line